


MULTIAQUA



TITLE	HEAT PUMP CHECK VALVE INSTALLATION	<p>NOTES:</p> <p>1. CHECK VALVE NEEDS TO BYPASS TXV IN THE HEATING MODE. ARROW DEPICTS REFRIGERANT FLOW IN THE HEATING MODE.</p> <p>2. INSULATE LIQUID LINE IF TXV IS INSTALLED AT THE CONDENSER</p>
AUTHOR	kjg	
DATE	05/18/07	
REVISION	0507400010	